

Cleaning and Disinfecting Instructions

Proper care and cleaning is essential to ensure a long life of accurate and effective weighing.

Caution: If the scale has a power adapter or battery charger, disconnect the scale from the power source prior to cleaning the unit.

- 1. Health o meter[®] Professional recommends using one of the following solutions on a soft cloth or disposable wipe:
 - mild soap and water solution
 - 70% isopropyl alcohol
 - solution with 1-5% hydrogen peroxide concentration

After cleaning/disinfecting, wipe with a cloth dampened with water and then with a clean dry cloth. To avoid residue build-up or damp surfaces, ensure the screen and scale parts are completely dry after cleaning.

- 2. Never use rough or abrasive materials to clean the scale, as these will damage the scale's finish.
- 3. Do not submerge the scale in water or any other liquid.
- 4. Do not pour or spray fluids directly on the scale.

